



GREEN AUCTION

LotNo	2180028	LOCATION	HAKATA-K
-------	---------	----------	----------

EXCAVATOR

80th Internet Auction 2019/06/13 ~ 2019/06/14

MAKER	KOMATSU	YEAR	1998
MODEL	PC128US-1	HOUR	7292
S/N	1710		

 DOCUMENT/書類
 UNABLE TO TRAVEL(START)/不働車

ENGINE	MODEL	S4D102E-1-A
	S/N	26236671
	COOLANT	OK
	OIL	OK
	START	OK
	BLOW-BY	YES/あり(SLIGHTLY/小)
	NOISE	NO/なし
	EPA	NO/なし
	NOTE	UNDER COVER, CONTROL VALVE MINOR OIL LEAKING. アンダーカバー コントロールバルブ オイルにじみ

FRONT ATTACHMENT	BOOM	TYPE	STD
			OK
	ARM	TYPE	STD
			OK TIP REINFORCED/先端補強
	PIPING		OK
	BUCKET	TYPE	STD
			BOTTOM CRACKED/底板割れ
	BLADE		-
	PINS	BOOM	OK
		ARM	LOOSE/ガタ
	BUCKET	LOOSE/ガタ	
NOTE			

CYLINDERS	BOOM	OK
	SWING	-
	ARM	OK
	BUCKET	OK
	BLADE	-
	NOTE	

TURN TABLE	LOOSE/ガタ
------------	----------

CONTROL	HYDRAULIC PUMP	OK
	TRAVEL	OK
	SWING	OK
	CONTROL	OK
	NOTE	

ATTACHMENT	-
------------	---

REMARK	
--------	--

UNDERCARRIAGE	SHOE	TYPE	STEEL
			<input type="checkbox"/> W/PAD
			500 mm
	PIN BUSH		OK
	CARRIER ROLLER		OK
	TRACK ROLLER		FALL OUT/脱落(LEFT 1PC.)
	FRONT IDLER		OK
	SPROCKET		OK
	NOTE	RIGHT REDUCTION GEAR FLOATING SEAL MINOR OIL LEAKING. 右減速機付近フローティングシールオイルにじみ	

CAB/CNP	CAB/CNP	DENT/へこみ GLASS MISSING/ガラス欠品
	ROPS	NO/なし
	SEAT	OK
	CONTROL LEVER	OK
	A/C OR HEATER	OK
	COMPUTER	OK
	MONITOR	OK
	BATTERY	OK
	NOTE	ACCELERATOR DIAL DEFECT. DOOR NOT CLOSE. アクセルダイヤル不良 ドア閉まり不良

ATTENTION/注意

*For unit required washing or repair, extra fee will be charge. The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
 *別途修理、洗車の費用がかかる場合があります。ご了承くださいませようお願いします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
 *Starting from 1st August 2017, for each successful bid a "Successful Bid Fee" will be charged
 *2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました